

Fourth Semester B.E. Degree Examination, Feb./Mar. 2022

COMPUTER AIDED MACHINE DRAWING

Time: 3 Hours Max. Marks: 100

Note: 1. Answer any ONE question from each of the parts A, B and C.

- 2. Use First angle projections only.
- 3. If any data is missing it may be suitably assumed and mentioned.
- 4. All the calculations should be on the answer sheet supplied.
- 5. All the dimensions are in mm.
- 6. Drawing instruments may or may not be used for sketching.
- 7. Part C assembly view should be in 3-D and other views in 2-D.

Part - A

- 1. An equilateral triangular pyramid of base side 40 mm and height 70mm rests with its base on HP such that one of its slant edge is parallel to VP. A sectional plane perpendicular to VP and inclined at 60° to HP cuts the pyramid by passing through one of its lateral faces at a height of 9mm above HP. Draw the front view, sectional top view and true shape of section.

 25 Marks
- 2. Draw the profile of
 - a. ISO Screw thread
 - b. ACME thread of pitch 40mm indicate all the proportions and dimensions. 25 Marks

Part – B

- 3. Draw the following view of a SOCKET and SPIGOT COTTER JOINT used to joining two rods of diameter 20mm (a) Sectional front view (b) A view looking from socket end.

 25 Marks
- 4. Draw sectional front view and side view of a Universal Coupling to connect two rods of diameter 20mm, indicate all dimensions. **25 Marks**

Part – C

- 5. Figure 1 shows the details of a screw jack. Assemble the parts of the screw jack and show the following views.
 - a. Half sectional front view showing the right half in section.
 - b. Top view.

50 Marks

- 6. Figure 2 shows the part drawing of a tail stock. Assemble the tail stock and show the following views.
 - a. Sectional front view showing the top spindle portion in section.
 - b. Left profile view.

50 Marks

18MEA406/18ME46A





Figure 1: Details of screw jack

18MEA406/18ME46A



SE SE Figure 2: Details of tailstock